



1710 Surge Feeder / SOIL HOPPER

TROUBLE	CAUSE	CHECK	CORRECTION
MACHINE WON'T RUN	POWER FAILURE	CHECK OUTLET POWER	USE DIFFERENT OUTLET
		CHECK ALL WIRE CONNECTIONS	TIGHTEN CONTACTS BACK
		MAKE SURE SWITCH IS "ON" POSITION	SWITCH ON
		CHECK VOLTAGE ON BOTH SIDE OF SWITCH	REPLACE SWITCH
	COMPONENT FAILURE	CHECK VOLTAGE ON MOTOR	NO VOLTAGE -REFER ABOVE
			CORRECT VOLTAGE-REPLACE MOTOR
		MANUALLY TURN FAN ON MOTOR	TURNS-REFER TO MOTOR
			WON'T TURN-REPLACE REDUCER
	CHECK BEARING FOR SIEZED	REPLACE BEARINGS	

*****WILL NEED VOLTAGE METER AND/OR SCREWDRIVER FOR MOST TROUBLESHOOTING*****

For Parts Quotes and/or Orders Call Kase (254)694-5846